

Areas at Risk of Flooding

- 1 Entrance into the village underneath the Railway Bridge, usually caused by a blocked drain, which should serve as an overflow to the ditches.
 - 2 Laurel Cottage, opposite to Cavendish Hall, and the crossroads, caused by lack of drains, local stream, old pipe work and insufficient drainage in surrounding fields.
 - 3 Norton Road, just past crossroads to Pakenham and Thurston Church, towards entrance to onion store, also further along low lying area marked as water meadows – liable to flood.
 - 4 Barton Road, just past farm near Barton Mere
 - 5 Heath Road, at junction of Barton Road, caused by infill of ditches
 - 6 Fishwick Corner (junction Mount Road and Barton Road), low lying and a drain problem
-