Areas at Risk of Flooding

- 1 Entrance into the village underneath the Railway Bridge, usually caused by a blocked drain, which should serve as an overflow to the ditches.
- 2 Laurel Cottage, opposite to Cavendish Hall, and the crossroads, caused by lack of drains, local stream, old pipe work and insufficient drainage in surrounding fields.
- Norton Road, just past crossroads to Pakenham and Thurston Church, towards entrance to onion store, also further along low lying area marked as water meadows liable to flood.
- 4 Barton Road, just past farm near Barton Mere
- 5 Heath Road, at junction of Barton Road, caused by infill of ditches
- 6 Fishwick Corner (junction Mount Road and Barton Road), low lying and a drain problem
- 7 Pockeridge Corner
- 8 Mount Road Fishwick Corner to Sow Lane
- 9 Beyton Road