

**THURSTON GRIT BINS - status at October 2020 Total 32**

<b>CLlr to Check</b>	<b>Location</b>	<b>Bin Status</b>	<b>Grit Status</b>
	<b><u>Barleyfields</u></b>		
BR	At the end of Barleyfields rear of No 38	Complete	FULL
BR	Near the Fire Hydrant	Complete	FULL
	<b><u>Barrells Road</u></b>		
BM	At junction with Church Road	Complete	FULL
	<b><u>Heath Road</u></b>		
JW	Junction of Heath Road and Genesta drive	Damaged/broken (1)	FULL
JW	Junction Heath Road and Maltings Garth	Complete	FULL
	<b><u>Barton Road</u></b>		
JW	Junction Barton Road and Heath Road	Complete	FULL/SOLID
JW	Fishwick Corner side of Railway Bridge	Complete	FULL/SOLID
JW	Junction Barton Road and Furze Close	Complete	FULL/SOLID
JW	Barton Road opposite Mill Lane	Complete	FULL
	<b><u>Norton Road</u></b>		
KT	Junction of Norton Road and Wren Close	Complete	FULL
KT	Junction of Norton Road and Meadow Lane	Complete	FULL
KT	Junction of Norton Road and Old Norton Road	Complete	FULL
BM	Junction of Norton Road and Pakenham Road	Overgrown/brambles	FULL
KT	Library Car Park at junction of Norton Road and Ixworth Road	Lid broken	RUBBISH
KT	Junction of Norton Road and Howes Avenue	Complete	FULL
	<b><u>Howes Avenue</u></b>		
KT	Junction of Howes Avenue and Lapwing Close	Complete	FULL
	<b><u>Church Road</u></b>		
KT	Junction Church Road and Norton Road	Overgrown/brambles	FULL
KT	Junction Church Road and School Road	Complete	FULL
	<b><u>Hollow Lane</u></b>		
BM	At Junction with Church Road	Complete	FULL
	<b><u>Pepper Lane</u></b>		
BM	Junction with Church Road	Complete	FULL
BM	Junction of Beyton Road	Complete	FULL
	<b><u>School Lane</u></b>		
BR	Junction of School Lane and Oakeyfield Road – end of footpath	Complete	FULL
	<b><u>School Road</u></b>		
BR	Junction of School Road and Sandpit Lane	Complete	FULL
BR	Junction of School Road and School Lane	Overgrown/brambles	FULL
BR	Junction of School Road and Victoria Close	Complete	FULL
BR	Junction of School Road and Birch Road	Complete	FULL
BR	Junction of School Road and Cavendish Close	Complete	FULL

	<b><u>Beyton Road</u></b>		
KT	Junction of Beyton Road and The Planche	Complete	FULL
KT	Junction of Beyton Road and Pokeridge Corner	Overgrown/brambles	FULL
KT	Junction of Beyton Road and The Acorns	Complete	EMPTY
	<b><u>Pokeridge Gardens</u></b>		
KT	On Pokeridge Gardens at junction with Thedwastre Road / Beyton Road	Complete	FULL
	<b><u>Fishwick Corner</u></b>		
KT	On junction with Mount Road	Complete	FULL

Key	Action required
	Village Handyman to attend site and rectify
	SCC Highways Department to fill
	Committee recommendation for a replacement – 2 No. new bins
1	Bin to be re-sited 5-6 yards from junction to prevent further damage being sustained